



Lloyd's Register of Shipping,

97 & 98, Scottish Provident Buildings,

Donegall Square West,

Belfast, 13th April, 1931.

Reference

S

The Secretary,
LONDON.



RETAIN

Dear Sir,

Steamer "KENNEBEC" - Belfast Report No.10,592.

In reply to your remarks in the Classing Letter of the 10th instant, the stiffening and repairs of this vessel were done in collaboration with the Senior Surveyor, Mr. G.R. Edgar, who visited the vessel. Your remarks regarding the attendance of a Senior in similar cases have been carefully noted.

With regard to the limit survey on the bedplate repair it was learned that the vessel had not experienced any heavy weather since the repair was effected, and in consequence it was considered inadvisable to suggest the removal of the limit survey date at this time. It is, in my opinion, an efficient repair and there are no signs, apparent, of movement of the patches or of their fastenings.

I am, Dear Sir,
Yours faithfully,

John K. Williams

W487-0148

© 2020

Lloyd's Register
Foundation

Refer to the Chief Engineer Surveyor's

14 APR 1931

Also for Mr. S. A. Hill to note.

*As it appears that Mr. Edgar made the usual
he should have signed this report with
the local Surveyor*



© 2020

Lloyd's Register
Foundation