

1 DEC 1915

Received by Chief Ship Surveyor 11. 12. 15.

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. S.S. ALBUERA".

Rpt.

Sws.

No. 13771.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Repairs

(New Donkey Boilers)

The class of this vessel is subject to some damaged shell plating being repaired at the first convenient opportunity.

The Swansea Surveyors now report: on removal of the donkey boiler the main deck in the donkey boiler house was found wasted, and has now been renewed, and the casings repaired as necessary.

It is submitted the vessel appears worthy to remain as classed, without fresh record of survey, subject as above.

as now subject etc.

M

M

13. 12. 15.

W490-0160



© 2020

Lloyd's Register  
Foundation