

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 8.12.15 When handed in at Local Office 9.12.15 Port of Swansea
No. in Survey held at Port-Pallat Date, First Survey 12.11.15 Last Survey 4.12.1915
Reg. Book. 528 on the Wood, Iron or Steel S.S. ALBUERA Master J.R. Ridland
TONNAGE:- Built at Port-Glasgow By whom Russell & Co. When 1902 3
GROSS 3460 Owners Bhr. Calvesen & Co. Port belonging to death
UNDER DE. 3208 Owners' Address
NET 2259 (if not already recorded in Appendix to Register Book)
Surveyed Afloat or in Dry Dock? Afloat Name of Dock Port Pallat Dock Destined Voyage Admiralty Service

WB=CellDBorDBa feet; uE&B feet; f feet; f feet; f
Total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 78044 Port Lon

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. for Special Survey. Date of last Survey and of Periodical Surveys.	Year and Month expired.	Machinery and Boiler Surveys (including date of N.B., if any).
100 A.1.		L.M.C. 10.13
4.14		B.S. 11.14
S.S. Ham. N°3-3.14		T.S. 4.14

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Repairs.

removal of the donkey boiler the main deck in the donkey boiler house found
verely wasted and now completely renewed; the casing at the after end of the house
tested thin near the deck and now efficiently doubled; three casing top plates over the
nkey boiler house renewed and one doubled.

See Boiler Report

DESCRIPTION OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Paired or Repaired								
Repaired or Repaired in place								
CONDITION OF THE	Stringers							
Inner Bottom Plating	Dblig. Plates under Sounding Pipes							
State if Tanks have been examined inside	Engine Room Skylights							
State if Tanks now tested	Coal Bunkers, Pipes, Lids, &c.							
Bulkheads	Scuppers							
Ceiling	Cargo Hatchways							
Cement or Asphalt	Hatches							
Rudder	Planking of Wood Vessels							
Steering gear and its connections	Caulking ditto							
Windlass	Treennails ditto							
Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto							
Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto							
Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto							
	Ditto ditto at other places ditto							
	Stringers, Clamps & Shells ditto							
	Salting ditto							
	(State if examined.)							
	Copper, or I.M. of Wood Vessels							
	(State if on Felt.)							
	When put on, Month Year							
	Boats							
	Masts, Yards, &c.							
	Condition now ascertained							
	(State if wedges removed)							
	Sails							
	Equipment letter							
	Anchors, No. of							
	Cables (State if now ranged)							
	" length size							
	(on board)							
	" Rule length size							
	Hawser & Warps							
	Standing & Running Rigging							

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptnd15, &c."

vessel is in an efficient condition and eligible, in my opinion, to remain
classed without fresh record of Survey.

(per Section 88) £
Age or Repair Fee (if any) £
Expenses (if chargeable) £
Surveyor's Fee (if any) £

Fees applied for,
10
Received by me,
10

Surveyor to Lloyd's Register of Shipping.

Character Assigned

TUE. 14 DEC. 1915

TUE. APR. 11. 1916

FRI. 1. OCT. 1919

TUE. APR. 20. 1920

W 490-0162

© 2020

Lloyd's Register
Foundation