

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office, \_\_\_\_\_ 10

# Lloyd's Register of Shipping.

(Report on Machinery, No. \_\_\_\_\_ Port \_\_\_\_\_)

10.128

## ENGINE FORGINGS ~~OR CASTINGS~~.

I have to report that the ~~Former~~ Steel Forgings ~~or Castings~~, as herein described, manufactured by Messrs. Soc. Esp. de Const. Naval of Reinosa the Engines No. \_\_\_\_\_ being constructed by \_\_\_\_\_

for the Ship No. 39, being built by Messrs. Soc. Esp. de Const. Naval of Sestas.

They have been inspected by me as set forth below, and found to be, so far as can be seen, sound & free from defects. These have been despatched to Sestas.

Engines or Castings.

G. Dixon.

Bilbao.

889 1  
31.60

CRANK SHAFT.	STRAIGHT SHAFTING.		
	THRUST SHAFT.	INTERMEDIATE SHAFTS.	PROPELLER SHAFT.
/	Ingot Steel.	/	/
	Elec. Furnace.		
	✓		
	✓		
	H.H. 1		
	39		
	180° Good.		
	22-5-31, 27-5-31, 22-7-31		

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

any chargeable) £  
paid at Bilbao

state whether scrap or puddled iron. If of steel, state whether made on the Open Hearth process.

WS13-0036

© 2020

Lloyd's Register Foundation