

NGTH on Deck 352 6 Moulded ... 50 7k Do. do. do. Second Dk. Beams 24 112 No. of Tiers

"REGISTER, NEWCASTLE"

TELEPHONE Nos G.P.O. 528 NATIONAL 1528.



# Lloyd's Register of British & Foreign Shipping,

## Collingwood Buildings, Newcastle-on-Tyne.

10th October 1911.

The Secretary,  
LONDON.

LLOYDS REGISTER,  
LONDON.  
RECEIVED 11 OCT 1911  
ANSP

Sir,

I am in receipt of your letter of the 7th instant, regarding First Entry report No. 61138 on the S.S. "ROTHLEY".

I much regret that I omitted to fill in equipment letter, the height of brackets above the tank margin at bilge and the tests of the stream & kedge anchors, which however has now been done.

With regard to the thickness of J & K strakes in way of bridge, I beg to inform you this is in order as stated on the report.

I am, Sir,

Your obedient Servant,

*L. J. Morrison*



© 2019

Lloyd's Register  
Foundation

WS2-0180

Round of Dk. Beams  
ches. ze in ship.  
7/8  
11/4, 45  
per a  
ches. ze in ship.  
Inches in Ship  
55  
5  
+42  
33  
+33  
57  
1/2 + 4

Lloyd's Register of British & Foreign Shipping  
Collingwood Buildings, Newcastle-on-Tyne

10th October 1911.

The Secretary,

LONDON.

I am in receipt of your letter of the 7th instant, regarding  
first entry report No. 6133 on the S.S. "ROTHMAY".  
I much regret that I omitted to fill in equipment letter,  
the height of brackets above the tank margin at bidge and the  
ports of the steam & kedge anchors, which however has now  
been done.

With regard to the thickness of J & K strakes in way of  
bridge, I beg to inform you this is in order as stated on the  
report.

I am, Sir,

Your obedient servant  
*J. J. Morrison*  
OCT 11 1911

Referred to the Chief Ship Surveyor.

*J. J. Morrison*



© 2019

Lloyd's Register  
Foundation