

COPY FOR LONDON OFFICE.

Lloyd's Register of Shipping.



Port Copenhagen

10th Marks 1921

This is to Certify that I have

Surveyed the Steel S.S. "Emlynton" ⁷⁰⁰/₃₄₂ Tons, of Cardiff, while she was afloat at this port and that I found she had been somewhat leaking, port & starboard sides, near the stringer and defender bars in Nos. 1 & 2 holds, also the door to crew space damaged, which is stated to have occurred on voyage

from the Tyne to Copenhagen with a Cargo of Coals, and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and

that I have Recommended that she be reexamined when she arrives at the Tyne, before taking in fresh cargo

being fit to ~~carry~~ proceed from Copenhagen to the Tyne in Ballast.—

Sgd. Jac v. Rosen

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

1/2 Embury and
Glas. Rpt. No. 6089.

OFFICE OF THE LONDON COAST GUARD

REGISTERED IN THE LONDON COAST GUARD

1700

1700

[Faint, mostly illegible handwritten text, possibly a list or account.]

[Faint handwritten text.]

[Faint, mostly illegible handwritten text at the bottom of the page.]



© 2010

Lloyd's Register
Foundation