

COPY.

Lloyd's Register of Shipping.

Port BOMBAY28th August 1933

This is to Certify that I have


Surveyed the Steel Screw Steamer "TACOMA" 6838 tons gross of
 HongKong, as she lay in Merewether Drydock, Bombay, for damage
 alleged due to grounding in the Red Sea,

and that I have transmitted to the Committee of Lloyd's
 Register of Shipping, London, a Report, stating that all ^{temporary} repairs
 recommended by me have been completed to my satisfaction, and
 that I have Recommended that she be continued in her present
 class viz :- 100 AI Shelter deck with freeboard without fresh
 record, subject to shellplating between wind and water being sealed
 at next drydocking and 15 fathoms of cable being repaired and
 retested,
 being fit to ~~sail~~ proceed to Japan to be broken up.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Committee or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Lloyd's Register
 W5494304