

COPY.

Lloyd's Register of British & Foreign Shipping.

71, Fenchurch Street, E.C.

18th March, 1909.

Gentlemen,

I have to inform you that it appears from a report received from the Society's Surveyors at Hamburg that the new Steamer "BUFFALO" built by the Flensburg Schiffsbau Ges., has left for your port where she will be docked either at Wallsend or Habburn for the purpose of effecting repairs required on account of damage sustained in launching. It is stated that the landing edge of C strake of plating in way of No.1 oil tank on starboard side is slightly indented for about two frame spaces in length, together with the floor and frame in way of same, and on the port side one plate slightly indented in the middle of a frame space.

I have to request that you will be good enough to give the case the necessary attention and report upon the same promptly on Form No.8 for the information of the Committee with a view to the classification of the vessel.

I am, Gentlemen,

Your obedient Servant,

The Surveyors,

NEWCASTLE.

R

Lloyd's Register
Foundation

W549-0210