

Im.1.39.

5 DEC 1939

11

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME MARDINIAN Rpt. MCH. No. 9799**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.")—Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey DOCKING


The Manchester Surveyors report this vessel placed in dry dock, bottom cleaned and coated, repairs ~~or renewals~~ to a deck plate and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 11-39 as recommended.

100 A.I.

11-39 MCH.

was
5-12-39



© 2021

Lloyd's Register
Foundation

WSS-0147