



Lloyd's Register of Shipping,

7261 AON T

71, Fenchurch Street,

London, 29th October, 1934

E.C.3.

R.

To the Surveyors at COPENHAGEN

TAP 103/34 (C1)

Vessel's Name

S.S. "VICTORIA"


No. in Reg. Bk. 87225

QUESTION.

The above vessel was reported in the Shipping Papers to have been driven ashore by high winds near the entrance to Backstairs Passage, South Australia, on the 5th instant.

No reply has been received to a casualty notice addressed to the Owners, and, in the circumstances, I shall be glad if you will kindly ascertain and let me know whether she has been abandoned as a total loss by all concerned.

A.K.D.



ANSWER.

Date:— 31st October, 1934.

We have communicated with the owners, who state that the above vessel has been abandoned as a total loss.

H. Langhorne
SURVEYOR TO LLOYD'S
REGISTER OF SHIPPING

This form is to be returned to the Secretary as soon as the information asked for has been filled in.

Im.1.34.

WS86-0288

© 2021

Lloyd's Register
Foundation

89766

4285-0588
for has been filled in.

82388

This form is to be returned to the Secretary as soon as the information asked

Handwritten signature/initials

RECEIVED BY THE SECRETARY
OF THE LLOYD'S REGISTER

Handwritten signature

Handwritten initials

a total loss of all concerned.
we know whether she has been abandoned or
that it has not finally disappeared and that
and in the circumstances I shall be
immediately notice addressed to the owners.
No reply has been received to the
the day instant.
Passenger, contrary to regulations, on
all high winds near the entrance to
shipping lanes to have been given reports
The above vessel was reported in the

abandoned as a total loss.
the above vessel has been
the owners who state that
we have communicated with

Date: 27th October, 1934.

QUESTION

ANSWER

Vessel's Name: "ALCANTARA"
No. in Reg. Bk. 82388

B.

To the Surveyors at COPENHAGEN

London, 27th October, 1934

Attest: Secretary

Lloyd's Register of Shipping

© 2021 Lloyd's Register Foundation

