

COPY.

Lloyd's Register of Shipping.



Port Singapore

27th, May, 1930

This is to Certify that I have

surveyed the Steel Screw Steamer "HUNTRESS" 4997 tons gross of
Singapore Town while in dry dock & afloat at this port after reported
damage in Deep Tank.

that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and


I have Recommended that she be continued as now classed
with fresh record of survey 5,30 subject to coamings being fitted
escape holes in tween decks or the openings closed at a
convenient opportunity or when the carriage of railway sleepers
has been completed. Stem bar & shell plating being faired at
first convenience & the lower hatch beams dealt with at first
convenient opportunity. After bulkhead of Deep Tank to be repaired.

is fit to carry Dry & perishable cargoes.

John F. Malley

Surveyor to Lloyd's Register.

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is
that neither the Committee nor the Society are under any circumstances whatever to be held responsible for
any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other
of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents



Lloyd's Register
Foundation

W582-0507