

1.

Sent to Chief Surveyors 27. 10. 03

Received from Chief Surveyors

VESSEL'S NAME *St. S. L. "Leona Morena"* Report *ELs.* No. *21253*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*First entry**When due*


+ 100 A1 ("Steel") "Span break"

1 DR (See) & Span DR (See) & deep framing

N.B = Cell DB a 120' a E 24' f 146' 7296 DTA 24' 5406 FPT996 APT426

FK 6BH Am. Lloyd's A&CP P31' B200' F40'

RETAIL


 27/10/03


© 2021

Lloyd's Register
Foundation

W582-0361