



Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 24th September, 1918.

Dear Mr. Warren,

Re. A.S. War Tempest.

I regret to notice that I have given the size of the upper deck stringer bar in wells as 6x6x.56 which is what was in the sister vessel "WAR SPRAY". In this vessel it is 5x5x.58 as per Midship Section sent with report.


I hasten to let you know lest the 1st Entry section might be commenced.

I would be glad if you would be so kind as to alter the report to make it agree with the Section and ship as built.

With kind regards

Yours faithfully,

J. Allan



© 2020

Lloyd's Register
Foundation

WS 89-0147

Height of Outside Brackets above at bilge
INNER BOTTOM PLATING, breadth and
thickness of Middle Line Strake

41	-	-	41	-	-
66	40	36	66	40	36

DECK. Iron or Steel, for
Wood Deck. Material & thickness
Third Deck Stringer Plate breadth & thickness