

S.S. Union

Nantes 11th July 1921

re line

Lloyd's Register of Shipping.

47, Quai de la Fosse,

Nantes, 30th July 1921

LLOYD'S REGISTER
LONDON.

RECD 2 AUG 1921

ANSR


THE SECRETARY

71, Fenchurch Street, 71

LONDON. E.C.3.

Dear Sir,

In reply to your letter of the 26th July, 1921, regarding the 1st entry report No 1224, on the machinery of the S/S "UNION", I beg to inform you that the joints of the liners on the working and the propeller shafts for this vessel have been made by running in anti-corrosive metal between the butts of the liners; 2 small grooves being cut on end of each liner to assist water tightness, thus:-



The Chantiers de Penhoët could not successfully braze weld these butts and it is respectfully submitted, since the shaft is considerably larger in diameter than would be required for one fitted with 2 liners, that it may meet with the favourable consideration of the Committee.

I am, Dear Sir,

Yours faithfully.

Geo. A. Poiré

W59 v 0025

meter of tubes 63.5 Pitch of tubes 100 x 92 Material of tube plates Steel Thickness: Front 25 Back 2

Referred to the Chief Engineer Surveyor.

Referred to the Chief Engineer Surveyor.

[Signature]

-2 AUG 1921



© 2021

Lloyd's Register
Foundation