

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor **27 JAN 1934**

VESSEL'S NAME Steel S.S. "CANBY" Rpt. ST.J No. 2490

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Remarks of Survey _____

The class is subject to indented plating port and starboard being faired at the Owners' convenience and to ^a damaged shell plate on starboard side aft being renewed on vessel's return to a home port.

The vessel requires to be specially examined in dry dock at the first convenient opportunity on account of grounding.

The Saint John, N.B. Surveyor/^{now} reports the vessel examined afloat and on account of damage through heavy weather, repairs effected to windlass, hatchways etc.

It is submitted action be deferred.



© 2021

Lloyd's Register
Foundation

WS99-0176