

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

29th December, 1933.

Dear Sirs,

With reference to the classification in the Society's Register Book of the steamer "LUFTWELL", I beg to acquaint you that the Committee have had before them today a report from the Society's Surveyors here from which it appears that the vessel has been examined afloat after grounding but no leakage was found.

The Surveyors state that upon enquiry regarding the port hawse pipe they were informed by the Master that this had been renewed.

They add that the hawse pipe was examined and found satisfactory.

In the circumstances it is recommended that the vessel be specially examined in dry dock at your convenience.

As you are aware the Special Survey No.2 became due last March, and it is understood that this inspection will be carried out sometime before the expiration of the year of grace.

I am, Dear Sirs,
Yours faithfully,

Messrs. The Anglo-American Oil Co., Ltd.,
36-38, Queen Anne's Gate,
WESTMINSTER,
S.W.1.

Clerk to the
Classification Committee.

Lloyd's Register
Foundation

7608-0047