

COPY.

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

1 Enclosure.

25th June, 1915.

Dear Sirs,

With reference to your first entry report No. 67678 on the steamer "SOUTHWESTERN MILLER", it is noted that in this case cattle doors are being fitted in the shelter deck 'tween decks in accordance with the approved plans, but that the work is not yet quite complete.

In view of the urgency of the matter, however, I enclose the first entry certificate of classification for the hull of the vessel which should be retained by you until the above work has been satisfactorily completed and all fees due in the case have been paid.

The machinery certificate is being forwarded to the Society's Surveyors at Hartlepool, and you should notify them immediately the above conditions are fulfilled. They are being requested to inform you of the payment of the fees for the survey of the machinery.

I am, Dear Sirs,

Yours faithfully,

The Surveyors,  
NEWCASTLE,



Secretary

© 2020

Lloyd's Register  
Foundation

It is concluded the tie plates on the 3<sup>rd</sup> deck in fore hold are 18" x .44 as in the case of the sister vessel and as approved but the Surveyor should state if this is so.

W. J. See letter dated 1.1.15

W. J. 25.6.15

n Dry Dock	
No. of Deck	
No. of Tier	
End up of Dk. Beam	
es. in p.	Inches Spacing Ship
1/8	53
de spac	
ker app	
es. in p.	Inches Spacing Ship

at Hatch

48

22 x 22

48

2 x 22

18