

240 0
Gro
Nag

W643-0147

COPY.

Lloyd's Register of Shipping.

Port OF PORT SAID.

3rd. October, 1930.

This is to Certify that I have

~~examined the Boiler and Machinery of the~~ and heard the diverse
~~report on propeller & stern bush, after clearing a rope which~~
~~was caught in it, of the S/S "MATOPPO", 78240 number in Register~~

that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

recommended that the record of remain as closed viz :-
+ L.M.C. M.S. 7-26.

to be made in the Register Book in the case of this vessel.

James Mackay

Engineer Surveyor to Lloyd's Register.

... certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
... Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is
... that neither the Committee nor the Society are under any circumstances whatever to be held responsible for
... in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book, or other
... the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents


Society."

11.37.

(per Section 28.)

... Expenses (if chargeable).....

Received by me,



Lloyd's Register
Foundation