

COPY FOR LONDON OFFICE
COPY.

No. 1289

Lloyd's Register of Shipping.



Port WELLINGTON

19th JANUARY, 1931.

This is to Certify that I have

Surveyed the ~~Boiler and~~ Machinery of the MOTORSHIP "ENTON" C.R.

4425 TONS & No. 70245 IN REGISTER BOOK OF SOCIETY FOR REPAIRS

TO CRACKED CYLINDER COVER.

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of REMAIN AS CLASSED WITHOUT

FRESH RECORD OF SURVEY.

be made in the Register Book in the case of this vessel.

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."