

F.E.

Received by Chief Ship Surveyor 23.4.14

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Sheels "Towyn"

Rpt. Son No. 8943

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 32.08


Depth "d" 9.96

Framing: Table No. 3 page 9. Description Single angle

Longitudinal No. 3538

Proportions  $\frac{\text{Length}}{\text{Depth}} = \underline{9.9}$

~~Deck~~ Sheerstrake as per Rule



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A-1 (Steel) as recommended

100 A-1 (Steel)

1 Dk (str-ws)

WTB = FPT 125

FK 3BH. Cam: Lloyds arcl. Fri

M  
23.4.14

© 2021



Lloyd's Register Foundation

W646-0181