

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

10th December, 1937.

Dear Sirs,

With reference to the classification in this Society's Register Book of the steamer "NIRITOS", I beg to acquaint you that this vessel's class is subject to some damaged bottom plating etc., and to the shell plating and framing in way of Nos. 1, 3 & 4 holds on the starboard side being repaired on the vessel's return, and, as it appears from the Shipping Papers the vessel arrived at Rotterdam on the 26th ultimo, I shall be glad if you will kindly let me know what arrangements are proposed to be made for this matter to receive attention.

I may add that the Third Special Survey No. 1, which became due at the end of September last, has been partly held and the vessel's class is also subject to some indented plating on the port side aft being dealt with at the Owners' convenience, and to a length of chain cable being supplied at the first convenient opportunity.

I am, Dear Sirs,

Messrs. Dracoulis Ltd.,
101 Leadenhall Street,
E.C.3.

Yours faithfully,

Classification Committee.

© 2021
Lloyd's Register
Foundation
W 65-0093