

R

Lloyd's
JMCB/10.

TELEGRAPHIC ADDRESS: "WEIRCO", ALD, LONDON.

TELEPHONES: AVENUE { 8974
8975
4970 (4 LINES).

ANDREW WEIR & CO.

HON. A.M. WEIR.	D. WEIR.
W. WEIR.	J.R. BROWN.
J.B. MORTON.	A.L. WEIR.
W.B. BROWN.	J. NIVEN.

LOYD'S REGISTER
RECEIVED
12 SEP 1927
And
LONDONBALTIC EXCHANGE BUILDINGS,
21 BURY STREET

LONDON, E.C. 3.

Ref. "H".

10th September, 1927.

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
E. C. 3.


Dear Sir,

S.S. "INVERAMPTON".

We beg to acknowledge yours of yesterday's date with reference to the survey of the Boiler and Tail Shaft of the above vessel.

We are looking into the matter and will communicate with you again as soon as possible. Our present intention is that the ship should be examined inside San Nicolas Harbour, Island of Aruba, for boiler and tail end shaft survey, and our Superintendent at Aruba will communicate with your Surveyor at Curacao on the matter. There is no drydock available at present, the docks in the vicinity being fully occupied for some time to come we regret to say.

Yours faithfully,



© 2021

Lloyd's Register
Foundation
W653-0199

Referred to Mr. S. A. Hill

Referred to Mr. S. A. Hill

12 SEP

[Handwritten signature]

1000 Exchange Building

51 WALL STREET

NEW YORK



© 2021
Lloyd's Register
Foundation