



# Lloyd's Register of Shipping.

53, Queen Square,

LLOYD'S REGISTER, Bristol, 2<sup>nd</sup> October 1918  
LONDON.

RECEIVED OCT 10 1918

ANSW

The Secretary  
Sir

With reference to your letter of 1<sup>st</sup> inst concerning First Entry Report of War Repair, I beg to inform you that the 3<sup>rd</sup> power was dispensed with at the request of the Board of Trade Surveyor Mr. Stephens.

The Report is correct in stating that beams are fitted on every frame on foistle as per instructions from J. Austin & Son dated 14<sup>th</sup> May to Builders, informing them that as the sheathing on deck was dispensed with, a steel deck .30 in thickness should be fitted with beams on every frame. I regret that this had not been marked by me on the plans in question.

I am Sir

Your obedient servant

P. A. Dyden



Lloyd's Register  
Foundation

W663-0135

W663-0136



SECRET & CONFIDENTIAL

Referred to the Chief Staff Surgeon

OCT 20 1918

101018

~~Sept 10 1918~~

*[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page.]*



© 2020

Lloyd's Register  
Foundation