



Lloyd's Register of Shipping.

31-32, Oxford Street,

Southampton January 31st., 1924.

**LLOYD'S REGISTER,
LONDON.**

REC'D 1 FEB 1924

ANSW

Dear Sir,

With reference to your letter, reference "S", of the 30th January regarding the S.S. "MAID OF SPETSAI", we beg to state that the pipe referred to is an iron inlet pipe $1\frac{1}{2}$ bore, connect- to the shell by countersunk tapped bolts, and to hand pump in forward W.C. for flushing same and according to the rules, does not require a storm valve to be fitted.

The discharge pipe to the W.C. was fitted with a storm valve at the ships side as the level of the waterline as required the rules.

The reports referred to in your letter are returned herewith.

We are, Dear Sir,

Yours faithfully,

Secretary,
LONDON.

pro the Surveyors.

John A. Lawson.



© 2021

Lloyd's Register
Foundation

W675-0279

W675 0279

