



Lloyd's Register of Shipping,

342, Argyle Street, Glasgow.

LLOYD'S REGISTER,
LONDON.

RECEIVED 17 MAY 1920

ANSW X

15th May, 1920.

Sir,

In reply to your letter of the 12th instant respecting Glasgow First Entry Report No. 39880 on the S.S. "EKARI", I beg to acquaint you that the Surveyor states that the rivets in butts of strake below sheerstrake are spaced 4 diameters apart as required.

I also beg to acquaint you, in reply to the second paragraph of your letter, that the Surveyor states that six liners are supplied and a spare oil pump has been fitted.

I am, Sir,

Your obedient Servant,

P. L. Warlow

Secretary to the
Glasgow Committee.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation


Wb82-0352

Referred to the Chief Ship Surveyor,
and the Chief Engineer Surveyor.

17 MAY 1890

Also for Mr. S. A. Hill to note.

M
18/5/20
noted in report
18/5/20



© 2020

Lloyd's Register
Foundation