

St. Not due 924 now held.
Machinery partly examined
on account of damage due
to grounding

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

to MC 126

5/26.

924.
30/1/26.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation