

REPORT OF TOTAL LOSS, CASUALTY, &c.

7982

No. 86056 in R. B. Wreck Book, p. 81 Date of writing this report 10th October 1928

Vessel's Name *Steel S.S. Thistleben* of *Sunderland* Tons (Net 2688 Gross 4589)

Built at *Sunderland* When *1924* 6 Casualty notice sent to Owner *8. 10. 28* Owner's reply *attached*

Owner's Name *Albyn Line Co. (Allan Black & Co. Mgrs)*

Address *Midland Bank Chambers, St Thomas St. Sunderland* SOURCE OF INFORMATION.

Case previously before *Date* *Particulars of Classification.* *100A1* *with forepeak* *9.28* *75(OA) 9.28*

Date of Casualty *4th October 1928*

Précis of particulars of Casualty

This steamer was sunk by collision off the Florida coast on 4th October 1928. The Owners concurs

THISTLEBEN.—London, Oct. 5.—The following cable has been received from New York—American steamer HANLEY collided with British steamer Thistleben today (Oct. 4). Latter sunk. HANLEY has forepeak leaking; proceeding New York.
London, Oct. 5.—British steamer Thistleben was sunk yesterday in collision with American steamer HANLEY. The collision occurred off the Florida coast. The crew of the Thistleben were taken on board the HANLEY, which is due in New York on Monday (Oct. 8). The forepeak of the HANLEY is reported to be leaking, but otherwise she suffered no great damage.

12610

Suggested Record *Sunk by collision 10.28*

Date of Committee *12 OCT 1928*

Committee's Minute *Sunk by collision 10.28*

