

71, Fenchurch Street, E.C. 3.

ALLAN, BLACK & CO

1-3 OCT 1928

ved by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME Steel Sc.Sr. "THISTLEBEN" Rpt. Sld. No. 29845

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey.....

This vessel has been placed in dry dock and the requirements of the S.S. No.1, due 6,28, complied with. The bottom has been recoated, 24 tank side brackets and lugs to floors in way re-riveted and minor repairs effected.

Two slight cracks in oexter plates repaired by electric welding.

It is submitted the vessel appears worthy to remain as classed with record of survey 9,28 and notation of S.S. Sld. No.1 - 28.

100 A.I.
with Rod
9.28 Sld
S.S. Sld No 1 - 28

Bk.



© 2021

1.10.28.

Lloyd's Register Foundation

11693-002

lett 1