

MANAGERS OF
BRITAIN STEAMSHIP CO. LTD.
THE WATTS SHIPPING CO. LTD.
RED ROSE LINE.

ID/IE

Your ref. "R"

Telephone No MONUMENT 2756 (5 Lines).


Telegraphic Address, WATTS, LONDON. (FOREIGN)

" " WATTS, STOCK, LONDON. (INLAND)

WATTS WATTS (INSURANCE) LTD.

SUPERINTENDENT ENGINEER'S DEPT.

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
LONDON. E.C.3.



Dear Sir,

s/s "WATFORD"

Further to your letter of the 16th ult., and our reply of the 17th ult., respecting the above vessel, we now have to inform you that she is, to all intents and purposes, a total loss, and we understand that Underwriters have disposed of the wreck to a firm of Shipbreakers in Canada.

In the meantime, the crew have been withdrawn and have returned to this country, and we see no reason why the record you mention in your letter of the 16th ult., should not be made against the vessel's name in the Register Book.

Yours faithfully,

For WATTS, WATTS & Co., LTD.

Idaniel
SUPERINTENDENT.



© 2021

Lloyd's Register
Foundation
74004
W696-0095

JOHN B. BISHOP
LONDON, ENGLAND
MEMORANDUM FOR THE RECORD

© 2021

Lloyd's Register
Foundation

Steel, redacted by

457 1001 1001

THESE EVIDENCES TWO EVIDENCES

Calculated to redacted
feeling no redacted
E. C. K. HODGSON

PROVINCIAL

After two days, the steel and to tested they at redacted
of steel was by, leaving evoked with redacted, the steel
Later a, regarding the steel in of, at side that they
and to be equal steel at the steel and the steel and the steel
abandoned in the steel and to with a of
steel the steel in red steel were and, the steel and in
the steel and the steel on the by the, the steel and in of
ed for the steel, the steel and to tested they in the steel
the steel and in the steel and the steel and the steel
the steel and the steel

Referred to Mr. Bishop.

- 8 OCT 1932

THE LLOYD'S REGISTER

PROVINCIAL