



COPY.

Lloyd's Register of Shipping,

High Close,
Wokingham, Berks.

se address
communications
is subject to
SECRETARY
to the following
initial.
& F.

NAME ROWAN BANK

17th February 1941.

S.S. "ROWANBANK"

Dear Sir(s),


I am directed to acquaint you that in accordance with the arrangements at present in force for the substitution of Special Periodical Surveys by successive General Examinations at twelve-monthly intervals, a General Examination for maintenance of class of the above-named vessel will require to be held before the end of **April next** and I shall be glad to learn, for the information of the Committee, when and at what port it is proposed to submit her for the requisite inspection.

At the same time I think it well to remind you that the vessel's Freeboard Certificate will expire on the **22nd April, 1941** and you will doubtless wish to arrange for the necessary Freeboard Survey to be held in conjunction with the above General Examination, with a view to the renewal of this certificate.

I am, Dear Sir(s),

Yours faithfully,

Messrs. Andrew Weir & Co.,
Superintendent's Dept.,
Birklands,
London Road,
ST. ALBANS. Herts.



Malcolm K Scott
Secretary.

Lloyd's Register
Foundation

WT1 - 0287 (1/2)

N:5 hold down etc + D.D. tank, much rigging, steering gear + wireless equipment
N:5 D.S. tank noted

Permanent repairs are required to the E.S. tank top plating forward (P.S) also in
floors + reverse frames in tank + E.S. bulkhead + 'tween deck bunker beam brackets

P.S.

I think it well to add that on the occasion of the survey, special attention will require to be paid to the condition of the engine room tank top plating forward (port side), the floors and reverse frames in the tank, the engine room bulkhead, 'tween deck bunker beam brackets and the forecastle deck plating.

1046
2-14-40

S.S. Rev. No. 105



© 2020

Lloyd's Register
Foundation

WT1 - 0287 (2/2)

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the