

Received by Chief Ship Surveyor 11-7-12

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Wood Schooner William Morton Rpt. Pmd No. 2935

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Nature of Survey

Half Emise

This vessel has been placed on blocks, the metal sheathing stripped and the vessel recaulked from keel to gunwale also the deck and remetalled on felt.

The requirements of the Hlf Time Survey which becomes due at the end of this year, have also been complied with, the mizzen <sup>mast</sup> ~~mast~~ renewed, the salting made good, and some further minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 7,12 and notations of H.T.  
Pmd 12, F & YM 7,12.

13 A1.7.12 PmdH.T. Pmd 12.F & Y M. 7.12.

© 2021

W 43 Bds

Boyd's Register  
Foundation

870048-714