

# Lloyd's Register of Shipping,

The Arsenal, Alexandria.

(Egypt)

E. ROBERTS,  
ENGINEER SURVEYOR

LLOYDS REGISTER  
LONDON.

REC'D APR 27 1916  
AN8D

7th April 1916

Your letter S, of the 24/3/16, re "MOORGATE"

Dear Sir

In reply to the above I beg to state, that the "MOORGATE" had four anchors on board, viz:- 2 bowers, 1 stream and 1 Kedge, and 255 fathoms of cable, viz:- 135 fathoms at Starboard, and 120 fathoms at Port, diameter of iron in link  $2\frac{1}{8}$ ". Am sorry I omitted to fill in these particulars on the report, entirely an oversight, through filling in the other details before actually writing the report. The cable on board in very good condition. The masts & yards found in good condition, *(Rasts in good condition)* "NESSIAN" Have noted your remarks for future guidance.

I am, Dear Sir

Yours faithfully

*J. Roberts*

The Secretary

Lloyd's Register of Shipping,  
London.



© 2020

Lloyd's Register  
Foundation

W726-0110

Lloyd's Register of Shipping

The Arsenal, Alexandria

(Egypt)

27th April 1916

LLOYD'S REGISTER  
LONDON  
REC'D APR 27 1916  
AN82

Your letter of the 24/3/16, re "MOORGATE"

Dear Sir

In reply to the above I beg to state, that the  
"MOORGATE" had four anchors on board, viz:- 2 bows, 1 stream  
and 1 kedge, and 255 fathoms of cable, viz:- 135 fathoms at  
starboard, and 120 fathoms at port, diameter of iron in link  
2 1/2". Am sorry I omitted to fill in these particulars on the  
report, entirely an oversight, through filling in the other details  
before actually writing the report. The cable on board in very  
good condition. The masts & yards found in good condition.  
"NESSIAN" have noted your remarks for future guidance.

I am, Dear Sir

Yours faithfully

Referred to the Chief Ship Surveyor

APR 27 1916

Also for Mr. S. A. Hill to note

The Secretary  
Lloyd's Register of Shipping,  
London.



© 2020

Lloyd's Register  
Foundation

Survey Fee (per Seco  
Transit on o