

*l by Chief Ship Surveyor*

*Received from Chief Ship Surveyor*

EL'S NAME

*Rpt.*

No.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

f Survey

Equipment

The Hull Surveyors report that a bower anchor and 60 fathoms of chain cable have been supplied to this vessel to replace those reported to have been lost.

It is submitted the vessel appears worthy to remain as classed without record of survey.

© 2020

Lloyd's Register  
3. 13  
Foundation

Mark L. P. H. - S. 18.06.9859

*Maker's Name*

Ship's Tonnage.						Is, Yards, &c.....
Weight of Bower Anchors, ex Stock.*	3½	4¼	5	5¾	6½	tion, how ascertained