

on 11 12.

1

Sent to Chief Surveyors 2.4.13

Received from Chief Surveyors

VESSEL'S NAME

SS. Shahzada Cambay

Report

No.

32498

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry

When due

+ 100 A.1 ("Skel") Indian Coasting

1 Dk (H) "Well Deck"

H.R. Cell Stf 114' 209t, F.P.I 35t A.P.I 36t.

F.H. 3 B.H. Cm. Lloyds A & P Q 105' B 20' F 24' Mch. Apt.

W.W. 13

It is concluded that the thickness of the keel buttstraps, amidships is in accordance with the Rules & not as stated in the Report but the Surveyor should be requested to state if this is so.

yes. 7.12.13



© 2021

Lloyd's Register Foundation

W769-0192