

T.S.S. "RODNEY STAR".

Plan showing opening proposed to be cut in the upper deck ~~deck~~ below the bridge, for ventilation purposes, in the insulated fruit space, submitted by the Glasgow Surveyors.

The Surveyors state that they have been informed by a Representative of Messrs. Goodwin, Hamilton & Co., that similar openings were cut in the "AFRIC STAR" and "STUART STAR" when similar alterations were carried out by Messrs. Vickers-Armstrongs, Ltd.

There does not appear to be any record in this Office of the cutting of ~~these~~ openings, nor of the compensation which was required *in way of same.*

In these circumstances it is submitted a copy of the Glasgow letter and the plan be forwarded to the Newcastle Surveyors, who should be requested to indicate ^{*in pencil*} on the plan the compensation which was required to be provided in the case of the "AFRIC STAR" and "STUART STAR".

At the same time the Glasgow Surveyors should be informed that the Newcastle Surveyors are being communicated with in regard to the matter.

By Mr. H. S. 20/1/32

g. m. m



© 2020
20. 1. 32.

Lloyd's Register
Foundation

W77-0131