

Em 10, 16

1

Received by Chief Ship Surveyor 21-6-17

Received from Chief Ship Surveyor 22 JUN 1917

VESSEL'S NAME: Steel S.S. "Silverburn"

Rpt. Hpl. No. 15344

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey DAMAGE.

Damage through Grounding & Collision.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	1	-					-
Removed and faired or repaired.....	-	-					-
Faired or repaired in place.....	1	1					1

Other items:-

Vessel examined in dry dock, bottom cleaned & coated
minor repairs effected.

M/M BOX 443

It is submitted the vessel is worthy to remain as classed with
record of Survey 6-17 as recommended

100 A.1.
6-17 Hpl.



© 2014
21-6-17

Lloyd's Register
W773-0087
Foundation

Survey Fee (per Sec. 50)
Special Damage or (per Sec. 50)