

5m.10.30.

W79-0006

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

APR 1892

VESSEL'S NAME

Steel Sc. "ISLEWORTH"

Rpt.

Pir.

No.

3230

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Nature of Survey

The Piraeus Surveyors report this vessel placed in dry dock, bottom examined and damage sustained to the stem, shell plating etc. through stranding.

Temporary repairs have been effected and the Surveyors recommend permanent repairs be carried out at the termination of the present voyage but should it be contemplated loading another cargo the vessel will require to be further specially examined.

The vessel is now under survey at Newcastle.

It is submitted action be deferred pending the receipt of a report from the Newcastle Surveyors.



© 2020

Lloyd's Register
Foundation

5.4.92
Haw

6.5

ACTER.
al Survey.
urvey and of
l Surveys.
Years
Assigned
expiry

board)
rule length
arser & Warns