

GROSS
UNDER DK.
NET

2m 13,16

WRECK BOX
No. 18 Bottom

Wreck 18

1

Received by Chief Ship Surveyor 12-2-'18

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "Harrogate" Rpt. Hul. No. 20,344

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

DAMAGE.

{ The class of this vessel is subject to some repairs being effected to stem plating, frames, stringer }
{ etc. on vessel's arrival at a Home Port, as per Rgn. Rpt. No. 1260. }

Damage through Collision

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	2	2			-	-	
Removed and faired } or repaired	-	-			-	-	
Faired or repaired } in place	4	3			3	1	

Other items:- Vessel examined afloat & minor repairs effected.

It is submitted the vessel is worthy to remain as classed without record of Survey as recommended & without special condition

as now, without etc.

Bluck
13-2-'18



© 2020

Lloyd's Register
Foundation
W864-0061