

# Lloyd's Register of British & Foreign Shipping

Surveyor's office, Stockholm.

Postal and telegraphic address: Lloyd's Register, Stockholm. Rikstelefon n:o 4161 & 3342.

LOYD'S REGISTER  
LONDON  
20 JUN 1914

The 17<sup>th</sup> June 1914

The Secretary

to the Committee of Lloyd's Register,

London,

Sir,

With reference to the contents of Your favour of the 4<sup>th</sup> inst. regarding the manufacture and material of the air receivers for Bolinder Motors - in particular for those now being fitted in the motor vessel "Kingsholm", I have repeatedly made enquiries at the Avesta Steel-works and, <sup>when calling on the works in telephone</sup> yesterday, have been informed, that Mr. Bengtson, the Manager of the Flanging and Welding Department of the Avesta works, has now returned home from Germany and will supply the necessary information in a few days.

In the meantime, I have obtained the enclosed blue print of the air receiver in question, showing that the wall thickness of the cylindrical shell is considerably in excess of the Rule, laid down in Secretary's letter of the 5<sup>th</sup> June 1912. Hoping to be able to supply Mr. Bengtson's further details re-

W872-0094



formations within a few days, I remain,  
Sir,

Your most obedient

@Hakson

1 blue print enclosed.

Referred to the Chief Engineer Surveyor.

C.B.A.

JUN 20 1914



© 2021

Lloyd's Register  
Foundation