

what special means, in the absence of internal examination, were adopted by the
rveyor to assure himself of the thorough efficiency of the

Brf 16457.

The Barry Surveyors state in their
report- that "The requirements in Specification
for Carrying oil fuel have been complied with"
In view of this statement, the Barry
Surveyors, it is submitted, should
be requested to state in detail exactly
what has now been done at their port.

T.P.S.
27.11.17.

M



© 2021

Lloyd's Register
Foundation

W813-0041