



# Lloyd's Register of British & Foreign Shipping,

Collingwood Buildings, Newcastle-on-Tyne.

LLOYDS REGISTER  
LONDON.

REC: 4 OCT 1904 3rd October 1904.  
ANS:

Reference

The Secretary,  
Lloyd's Register.

Sir,

In reply to the classing letter of the 30th ultimo relating to the s/s "CAYO MANZANILLO", Newcastle report No 47661, I beg to state that the size of the steel wire rope was given in error as  $3\frac{1}{2}$ " instead of  $3\frac{1}{4}$ " as supplied. With reference to the reverse frames, those given on the first entry report are in way of the double bottom, the reverse frames in after peak are  $3\frac{1}{2}$ " x 3" x  $\frac{8}{20}$ " as per approved midship section, and bulb angle frames 6" x 3" x  $\frac{10}{20}$ " are fitted in the fore peak.

I am, Sir,

Your obedient servant,

*James McNeil*



© 2020

W880-0023

Lloyd's Register  
Foundation

Referred to the Chief Ship Surveyor.

C.S.S.

4 OCT. 1904

Also for Mr. S. A. Hill to note

RECEIVED  
4/10/04

C.S.S.



© 2020

Lloyd's Register  
Foundation

Gross  
Less C  
Less d

ated by  
SSEL'S  
The rem