

TELEPHONE NO  
32 BRIERLEY HILL.

TELEGRAMS:  
"TAYLORS, BRIERLEY HILL."

**SAMUEL TAYLOR & SONS (BRIERLEY HILL) LIMITED,**

LLOYDS REGISTER CHAIN, CABLE & ANCHOR MANUFACTURERS,  
LONDON.

**BRIERLEY HILL,**

STAFFORDSHIRE.

RECD MAR 11 1916

ANSD

13

10th March 1916.

The Secretary,

Lloyds Register of Shipping,

L O N D O N , E.C.

*John Hanson*

Dear Sir,

No. 158 Ship.  
Messrs John Crown & Sons Ltd.

The above firm inform us that your Surveyor has rejected the Kedge Anchor supplied to thier No. 158 Ship, on account of it being 26 lbs below the Table weight. The gross weight is alright, as the Stock is  $\frac{1}{4}$  cwt over. This being the case we are sure you will agree to allow the Anchor to pass in this instance.

We shall be very glad to hear your permission has been given for it to be accepted, especially considering the difficulty there is in getting Anchors at present.

Yours faithfully,

For SAMUEL TAYLOR & SONS,  
(BRIERLEY HILL) LIMITED.

© 2020  
Lloyds Register  
Foundation  
COMMERCIAL SECRETARY.

W904-0195

Referred to the Chief Ship Surveyor.

FRNB  
MAR 14 1916

Submitted Messrs Taylor &  
informs of the Committee's decision  
re. Sec 20 letter to the Sps dated 1.3.16  
16/3/16

© 2020



Lloyd's Register  
Foundation

EMBERTEX HIT  
SANDER TAYLOR & SONS LIMITED