

Less above Crown of
Engine Room ...
FOR FRES

61.25
3393.46

Proportions—Depths to Length—Upper Deck Beam at
side to top of keel

✓11.40

Residence 25 Broad St. New

87ms.4.13.

LOYDS REGISTER
LONDON
3 FEB 1914

REC
ANCE

Time of Receipt

4-35

TELEGRAM.

POST OFFICE TELEGRAPHS.

If the Receiver of an Inland Telegram doubts its accuracy, he may have it repeated on payment of half the amount originally paid for its transmission, any fraction of 1d. less than 1d. being reckoned as 1d.; and if it be found that there was any inaccuracy, the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams.

Handed in at	Office of Origin and Service Instructions	Words	Charges to pay
337	Amsterdam	19	

Office Stamp.


RECEIVED
FEB 3 1914
4.20 P

THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM. Received here at

TO { Committee London

Steamer eruption survey
completed reports being
forwarded tonight engine
fee will be
paid tomorrow or
Thursday Surveyor

Information phoned to Mr Denton - also
safe (per phone) from Sld. That Machinery fee
promised this afternoon. Mr. Denton would
to hear tomorrow when the case is in



© 2020

Lloyd's Register
Foundation

W912-0129

W912-0129

Referred to the Chief Ship Surveyor
and the Chief Engineer Surveyor.

7 Feb

FEB -3 1914



© 2020

Lloyd's Register
Foundation

12
words,
including
the words
in the
address.
6 D.
Every
additional
word,
1
2 D.

When a reply
is required,
the words
are n

Pre
Off

PR

CIA

EU

Less Cre
Es above
Engine
KONNAGH