

COPY.

Enclosure.

13th January, 1908.

Gentlemen,

E. With reference to your first entry report No.2590 on the machinery of the Steamer "COLBERT" I have to return herewith the plan of the main boilers and to request that you will state whether these boilers have been built in accordance with the approved plan, in view of the statements in your report that the thicknesses of front plates at bottom are $1 \frac{9}{32}$ " + $\frac{1}{16}$ ", thickness of lower back plate $\frac{13}{16}$ ", diameter of plain tubes $3 \frac{3}{4}$ ", and greatest pitch of stays at lower back plates 5'9", as these sizes do not correspond with the approved plan.

I am, Gentlemen,

Your obedient servant,

Secretary.

The Surveyors,

HAVRE.



© 2021

W932 0121

Lloyd's Register
Foundation