



Lloyd's Register of British & Foreign Shipping,

Collingwood Buildings, Newcastle-on-Tyne.

LLOYDS REGISTER
LONDON. 29th July 1915.

RECD 30 JUL 1915

ANSD

Reference

S. The Secretary,
London.

Sir,

In reply to the inquiry contained in your
Classing Letter of the 27th inst. respecting the Propeller
shaft of the S.S. "Beaufort", Newcastle report N° 64465,
I beg to state (on the absence of Mr Cooper on holiday)
that a clerical error has crept into the report
which states that this shaft is fitted with a continuous
liner. In this case there are no liners on the
Propeller shaft.

I am

Sir

Your obedient servant

Wm R. Austin.



© 2021

Lloyd's Register
Foundation

W951-0034

Referred to the Chief Engineer Surveyor.

C.S.A.

Also for Mr. S. A. Hill to note.

JUL 30 1915

Noted
S.A.H.
29-7-15

Received from Mr. S. A. Hill

29-7-15

RECEIVED

20 JUL 1915

LONDON

RECEIVED REGISTER



© 2021

Lloyd's Register
Foundation