

DESCRIPTION OF DYNAMO, ENGINE, ETC.
One multipolar compound wound dynamo coupled direct to open type vertical en

TELEPHONE: No. 173 SUNDERLAND.



Lloyd's Register of Shipping,

55, Fawcett Street,

1 Encl.

Sunderland, 4th December, 1915.

LLOYDS REGISTER
LONDON
5 JAN 1915
REC-
ANSE

Reference

E The Secretary,
London.

Sir,

I herewith return the report on the electric light installation of the S.S. "BEEMAH" the particulars in regard to resistance of installation and compass adjustment being now filled in.

I very much regret the delay in forwarding this report which had been inadvertently mislaid amongst some papers in my desk.

I am, Sir,

Your obedient servant,

J. Y. Hindlay



© 2020

Lloyd's Register
Foundation

W954-0114

Joints in cables, how made, insulated, and protected

there are none.

Referred to the Chief Engineer Surveyor

FKW

Also for Mr. S.A. Hill to note:

[Handwritten signature]

JAN 5 1915

RECEIVED

JAN 5 1915

RECEIVED

[Faint, mostly illegible text, possibly bleed-through from the reverse side of the page]



© 2020

Lloyd's Register Foundation