

No. above Crown of
Engine Room ...
Gross Tonnage 3681.40

Longitudinal Number 25900
Depth "d." at middle of length (See Secs 2 & 13) 16.1

Owners - Lower



SWAN, HUNTER, & WIGHAM RICHARDSON, LIMITED,
Shipbuilders & Engineers,
WALLSEND AND WALKER.

Branch Office: 7, East India Avenue, London, E.C.

ALL OFFERS ARE SUBJECT TO OUR USUAL STRIKE, ACCIDENT
AND GUARANTEE CLAUSES AND TO THE OTHER CONDITIONS
IN OUR PRINTED FORM OF CONTRACT.

ENCLOSURES.

The Secretary,
Lloyd's Register of Brit. & Foreign Shipping,
71, Fenchurch Street,
London E.C.

Dear Sir,

No. 916: M.V. "Arum".

After communicating with your Newcastle office this
afternoon we telegraphed to you as per copy enclosed. The
Owners of the vessel wish to have the certificates for this
vessel in their possession tomorrow. We trust that our tele-
gram was not too late in reaching you this afternoon, and that
you can oblige us by arranging for the Classification Certifi-
cate to be sent to our London office tomorrow forenoon.

Yours faithfully,

For
SWAN, HUNTER & WIGHAM RICHARDSON, LTD.

R. H. W. W. W.
SECRETARY.



© 2020

Lloyd's Register
Foundation

Telephone:- POST OFFICE No. 401: NATIONAL
No. 9, Wallsend - for trunk messages.
Passenger railway stations: WALKER (Riverside Branch) 1/2 mile. WALLSEND 1 mile.

"	In way of Long Bridge	24 1/2	24 1/2	"	"	"	breadth & thickness
"	Spacing	11 3/4	11 3/4	"	"	"	Angles on ditto, No.
BEAMS, Second Deck, Single Angle Bulb		11 3/4	11 3/4	"	"	"	Tie Plates outside Hatchw

For Mr. Meyer

Co.

MAY 26 1914

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED



© 2020

Lloyd's Register
Foundation

BEAMS, Second Deck,
Spacing
In way of Long

No. of excess of Hatchways
Engine Room
Cross Tonnage
36