

GLASGOW REPORT No. 54981

(COPY)

MACLAY & McINTYRE LTD.

21 Bothwell Street,

Glasgow, 27th Sept. 1934

Messrs D. & W. Henderson & Co. Ltd.
 Meadowside Works,
 GLASGOW. W.1

Dear Sirs,


S.S. "LOCH LOMOND"

With reference to your letter of the 26th inst., we herewith confirm having arranged with you to dispense with the bulkhead between Nos. 2 and 3 holds, and where at present a partial bulkhead is fitted. We trust that this letter will meet with Lloyds requirements.

Yours truly,

(Sgd) MACLAY & McINTYRE LTD.

J.F. MacLay, DIRECTOR



© 2020

 Lloyd's Register
 Foundation

Are Frame and Reversed Frame
 joggled?.....
 Bracket Floors, breadth and thickness at
 middle line.....

33"

38"

Spacing

Forecastle Deck, Angle, E or F