

2

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

24 JUL 1940

VESSEL'S NAME LANGLEEGORSEReport GLS.No. 62595**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

1ST S.S. No. 3 due 3-39**ADVANCED
PARTLY HELD.**

When proposed to be completed (GEN. EX. AGREED TO BY LIV. COM. TILL 4-41 WITH RECORD EXAM. 4-40)

The greater part of the Survey has been held
To complete the S.S.:— See Report.

Repairs are required to the bunker screen bulkhead at S.S.

WAG
18.7.40



© 2020

Lloyd's Register
FoundationS.S. PART HELD RFS

W982-0136