

"MARKAY"

For the attention of Mr. Potts.

Mr. Stocks, the Principal Surveyor Bristol Channel, telephoned to say that Mr. Finnigan, the Owners' Representative for the above vessel would be calling at the London Office on Monday morning at 11 a.m., with full plans and particulars of the recommendations which he, Mr. Stocks, had made in order to enable the vessel to proceed to a permanent repair port, if necessary.

Mr. Stocks added that he had asked for 25% of the longitudinal strength on the bottom forward, in order to enable the vessel to leave the Bristol Channel, but in view of the fact that these temporary repairs may be carried out at another port, he thought it well that details should be approved in the London Office.

CB
8.1.44.

P.S. I shall be back as soon as possible; am at the Swedish Consulate
CB



© 2020

Lloyd's Register
Foundation

REGISTERED IN ENGLAND
under the Companies Act, 1900
and in the United States of America
under the Act of March 3, 1879
for the purpose of carrying on
the business of a public utility
company.

This vessel, in our opinion, is eligible to continue as now classed as a Category 1 vessel, subject to permanent repairs to forward bottom, side shell, inter-